

新北市立南勢國民中學 114 學年度飲水機定期更換濾芯成果報告

114 年 11 月-B、C 棟教學區公共空間

	更換前	更換後
C 棟 1 樓	 A single water dispenser with a digital display showing '98' in red. The filter housing is open, revealing the old, yellowed filter.	 The same water dispenser with the digital display still showing '98'. The filter housing is now closed, and a new, white filter is visible inside.
C 棟 2 樓	 Two water dispensers side-by-side. The left one has a digital display showing '88' in purple. The right one has a digital display showing '80' in blue. Both have their filter housings open, showing old, yellowed filters.	 The same two water dispensers. The left one now has a digital display showing '98' in green. The right one has a digital display showing '97' in yellow. Both filter housings are closed, and new, white filters are visible inside.
C 棟 3 樓	 Two water dispensers side-by-side. The left one has a digital display showing '99' in green. The right one has a digital display showing '97' in green. Both have their filter housings open, showing old, yellowed filters.	 The same two water dispensers. The left one now has a digital display showing '99' in red. The right one has a digital display showing '99' in blue. Both filter housings are closed, and new, white filters are visible inside.

C 棟 4 樓



B棟1樓



B棟2樓



B棟3樓



B 棟 4 樓



B 棟 5 樓

